



1st July 2024

HRV 5" Controller Firmware Update to V1.7.6 via Wi-Fi

(For AirSense & Classic Pro)

Firmware Upgrade Procedure

'PRESS'

MENU


Previous

Advanced

Wi-Fi

Setup


This takes you to the Wi-Fi screen (see below):



Ensure the controller is connected to the local Wi-Fi (if not already done) then,

PRESS & HOLD the top grey block (the one with the SSID in it)

“**WPS Connect**” button will change to the words “**Upgrade Firmware**” (see below):



'PRESS'

Upgrade firmware

Wi-Fi & Cloud fields will change to **Please Wait**

IF POWER IS DISTURBED AT THIS POINT, THEN THE UPDATE WILL FAIL

When the upgrade has completed, Wi-Fi will change back to **Connected** and Cloud to **Available** (as above screen-shot).

This will take around a minute to complete.

If in the rare case that you get “**Wi-Fi Connected**” and “**Cloud Not Available**”


Press “**Restore defaults**”. The Wi-Fi will change to ‘**Not Connected**’ & the Cloud will change to ‘**Not Available**’.

Turn Wi-Fi Module to **OFF** (slider switch)

Then Turn the Wi-Fi Module to **ON**

Wait around 30 seconds for “**Wi-Fi Connected**” and “**Cloud Available**” to appear.

If connection does not happen, then press and hold the top grey block again (with the SSID in it), until the **WPS Connect** and **Manual Connect** buttons reappear.



Then reconnect to the Wi-Fi (WPS or Manual).

If after you have completed these steps and the Cloud is still **Not Available** recheck that the internet connection (Not Working, out of data etc.)